

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

JAMES K. HILL & SONS PICKLE WORKS  
(Santa Fe Lofts)  
1001-1007 East First Street  
Los Angeles  
Los Angeles County  
California

HABS CA-2792

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Michael Kenneally, Robert Taylor, photographers, August 2006

CA-2792-1	View of west front of Pickle Works Building, facing northeast
CA-2792-2	View of west front of Pickle Works Building, facing southwest (note scale stick against garage bay)
CA-2792-3	View of north side of Pickle Works Building, facing southwest
CA-2792-4	View of north side of Pickle Works Building, facing southeast
CA-2792-5	View of east rear of Pickle Works Building, facing southwest
CA-2792-6	View of east rear of Pickle Works Building, facing northwest
CA-2792-7	Contextual view of Pickle Works Building, taken from north parking lot, facing west
CA-2792-8	Contextual view of Pickle Works Building, taken from South Santa Fe Avenue, facing south
CA-2792-9	Detail of west front of south end of Pickle Works Building, adjacent to First Street Viaduct, facing east
CA-2792-10	Detail of east rear of south end of Pickle Works Building, adjacent to First Street Viaduct pylon, facing west
CA-2792-11	Detail of string course and frieze of Pickle Works Building, facing west

JAMES K. HILL & SONS PICKLE WORKS

HABS CA-2792

INDEX TO PHOTOGRAPHS

(Page 2)

CA-2792-12	Detail of historic replacement door on west front of Pickle Works Building, facing east
CA-2792-13	Detail of raised basement window on west front of Pickle Works Building, facing east (note scale stick)
CA-2792-14	Detail of second floor long casement windows of Pickle Works Building, facing east
CA-2792-15	Detail of second floor small casement windows of Pickle Works Building, facing east